CORRESPONDENCE NO.:1 Page 1 of 3

FIRE/LIFE SAFETY INSPECTION REPORT

ADULT/JUVENILE DETENTION FACILITIES

Facil	ity:					TY TYPE: (check one
			\mathbb{C}	OPY	Adu [] Juve []	It max/med security It minimum security enile max/med securit enile minimum securit
S	TANISL	4-0003-000-040-L AUS CO JAIL			[] Hold	ling Cell(s) only
	05 12T ODESTO	• = •	95354			
An ir Code	nspection e, and ap	of this facility was conduc plicable requirements of T	cted per the mandat Titles 19 and 24, Cal	e of Section 13146.1 ifornia Code of Regu	, California Healt lations. (Check	h and Safety appropriate box)
-	[]	No deficiencies affection	ng fire/life safety we	re noted. Fire cleara	nce is granted.	,
. "	×	Minor deficiencies affe Fire clearance granted		were noted and are p	ending correction	n
	[]	Fire clearance is withh attached).	neld pending correcti	ion of deficiencies. (List of deficiencie	es is
	[]	Prisoners are no longe	er detained at this fa	cility.		
bel	ow. <i>Wh</i> e	conducting the inspection of fire/life safety deficient of the State Fire & Life Safety Division P.O. Box 944246 Sacramento, CA 94244-2 FAX: (916) 324-3784	cies are noted, a list Marshal on	of the deficiencies m	iust accompany t	his report.
		Board of Corrections Facilities Standards & C 600 Bercut Drive Sacramento, CA 95814 FAX: (916) 327-3317		.		SOARD OF SUPER
	•	Official in Charge of the Local Governing Body		ervisors, City Coun	cil, etc.)	ERVISORS A II: 02
	•	pection: 10-2-0		Inspected b	y: CMOS	SMAN
Fi	re Authori	ty: /90Dē\$ <u>76</u>	FIRE DEPT			
Fa	cility Rep	resentative (E. RADZA S	SGT Shee	A DEPT

CORRESPONDENCE NO. 1 Page 2 of 3

AUULI/JUVENILE DE LENTION FACILITY INSPECTION GUIDE

The following is to be used only as a guide and is not intended to include all applicable codes and requirements.

Δ.	CONSTRUCTION	Yes	No	N/A				
	 Building construction type and fire resistive rating conform throughout and are maintained in good repair. (19 CCR 3.24; CBC 308.2.2.2; CBC 324A.1; CBC 324A.2; CBC Table 6-A) 	X		[]				
	2. Proper interior celling and floor finish ratings are provided. (CBC 324A.4, CBC Table 8B)	[]	[]	M				
	 Vertical shaft enclosures are in good repair and fire assemblies at openings are properly maintained. (CBC 711, Table 6A) 	×	[]	[]				
В.	EXITS							
	 Proper corridor construction and opening protection are provided and maintained. Dead-end corridors do not exceed 20 feet in length. (CBC 1004 through 1006). Exit balconies do not exceed 50 feet. (CBC 332A.4) 	" 📈	[]	[]				
	5. All means of egress are unobstructed and free of storage. (19 CCR 3.11)		[]	[]				
,	6. Means of egress and exit signs are installed, illuminated and maintained. (CBC 1003.2.8.2 through 1003.2.9.2; CBC 331A.5)	X	ii	ij				
•	 Corridors are not used as part of the air distribution system. (CMC 602.1) Supervisory personnel are continually on duty and effective provisions are made to remove occupants in case of fire or other emergency. 	X						
	(Penal Code 6030[c]; CBC 1003.3.1.8 exception 3)	fit T						
C.	MECHANICAL/ELECTRICAL							
•	9. Fire and smoke dampers and similar devices are adequate, properly installed, maintained and tested. (CMC 606.1 & 2; CBC 713.10, 713.11)	M	[]	[]				
÷	10. All heating, cooling and ventilation equipment is maintained satisfactorily. There are no visible defects. (CMC 109.2; 19 CCR 3.02)	M	[]	[]				
-	 Electrical wiring, fixtures and appliances are properly installed and operated. (19 CCR 3.01; CBC 3.24) 	M	[1]	[1				
	 Emergency power is provided for minimal lighting and fire/life safety systems. (CBC 1003.2.9; CBC 328A) 	X	[]	[]				
D.	HOUSEKEEPING							
	 Kitchen hoods, vents, ducts and filters are installed, adequate, are maintaine in proper condition and are free of grease. (19 CCR 3.19, 3.24; CMC 501 through 510) 	d 💢	[]	[]				
	14. All areas are free of unacceptable amounts of storage. (19 CCR 3.19)	3.11) torily.						
E.	FIRE EXTINGUISHING/FIRE ALARM 15. All portable fire extinguishers, automatic fire sprinkler systems, wet and dry	Μ	ГТ	r 1				
	standpipe systems are installed and maintained properly. (19 CCR 3.24; 19 CCR 3.29; 3.29A; NFPA 13)	*1		f 1				
	16. Manual and automatic fire alarm systems, when installed, shall be properly installed and maintained. (19 CCR 3.24; CBC 330A; NFPA 72)	X	[]	[]				
	17. The automatic fire alarm system is properly maintained. (19 CCR 3.24)	M	[]	[]				
F.	TRAINING/PREPLANNING	_						
	18. At least one person is on duty who meets the training standards established for general fire and life safety relating specifically to the facility.	X.	[]	[]				
	(Penal Code 6030[c]) 19. Fire suppression preplanning inspections are conducted by the local fire authority at least every two years. (Penal Code 6031.1)	X	[]	- []				

Code references above are from the most recent SFM adopted codes. Note that code references for the CBC may be different for facilities constructed prior to the revision of this form.

Where any deficiency is identified, please provide specific information regarding the deficiency type and location (e.g., the fire alarm in Building C indicated a trouble alarm and must be repaired.)

CORRESPONDENCE NO. 1 Page 3 of 3



MODESTO FIRE DEPARTMENT

P.O. BOX 642 MODESTO CA 95353 1010 10TH STREET STE. 3200 (209) 571-5553



FIRE SAFETY NOTICE

I-Inspection - Initial Annual FPB Assigned To MOSSMAN, Craig on 10/2/2008

Start Date: 10/2/2008 7:40:26AM STANISLAUS CO JAIL

Business Name: Address: 805 12TH ST

City/State/Zip:

MODESTO, CA 95354

Finish Date: 10/2/2008 10:35:56AM

Occupancy ID: 3149

Station No.: Station 01

Business Phone: (209)525-7905

The Modesto Fire Department, in accordance with the current California Fire Code (CFC), Modesto Municipal Code (MMC), and California Code of Regulations Title 19 (T19), requires compliance with the listed items below:

Occupancy Information

Complex Information

Occupancy Use: 13 - Mental Hospital, Sanitarium, Jail, Priso

Property Uses: 361 - Jail, prison (not juvenile)

Commercial Units: 0

Residential Units: 0

Violations

Date Found

Date Cleared

Standard/Reference

ELECTRICAL

Hazards

10/02/2008

[S] CFC / 8504

When electrical hazards are identified, measures to abate such conditions shall be taken

1. KITCHEN ELEC PANEL SPACER

HAZ MAT

No smoking in hazardous areas

10/02/2008

[S] CFC / 1109.4.1

When it is determined that smoking constitutes a fire hazard, "NO SMOKING" signs shall be posted

- 1.DEISEL TANK-NO SMOKING AND FLAMABLE SIGNS ON ALL FOUR SIDES OF CAGE.
- 2.LABEL EMERGENCY SHUT OFF SWITCH

SYSTEMS

General maintenance

10/02/2008

[S] CFC / 1001.5.1

All fire protection systems shall be maintained in an operational condition at all times and shall be repaired where defective.

- 1. PAINTED SPRINKLERS HEADS IN LAUNDRY -REPLACE
- 2. IWQ BATH RM HEADS PAINTED-REPLACE

Rolling Fire Door Test

10/02/2008

[S] CFC / 1111.2.4

Horizontal or vertical sliding or rolling fire doors shall be inspected and tested annually by the owner or authorized representative to check for proper operation and full closure.

KITCHEN

Recipient Signatu	re
-------------------	----

ERNIE RADZA

A re-inspection shall be made on or after 10 / 23 / 2008