

FIRE/LIFE SAFETY INSPECTION REPORT

ADULT/JUVENILE DETENTION FACILITIES

Facility: Stanislaus County Juvenile Hall
2215 Blue Gum Ave

FACILITY TYPE: (check one)
 Adult max/med security
 Adult minimum security
 Juvenile max/med security
 Juvenile minimum security
 Holding Cell(s) only

An inspection of this facility was conducted per the mandate of Section 13146.1, California Health and Safety Code, and applicable requirements of Titles 19 and 24, California Code of Regulations. (Check appropriate box)

- No deficiencies affecting fire/life safety were noted. Fire clearance is granted.
- Minor deficiencies affecting fire/life safety were noted and are pending correction. Fire clearance granted
- Fire clearance is withheld pending correction of deficiencies. (List of deficiencies is attached).
- Prisoners are no longer detained at this facility.

The authority conducting the inspection shall submit copies of this report to the appropriate bodies listed below. Where fire/life safety deficiencies are noted, a list of the deficiencies must accompany this report.

- Office of the State Fire Marshal
Fire & Life Safety Division
P.O. Box 944246
Sacramento, CA 94244-2460
FAX: (916) 324-3784
- Board of Corrections
Facilities Standards & Operations Division
600 Bercut Drive
Sacramento, CA 95814
FAX: (916) 327-3317
- Official in Charge of the Facility
- Local Governing Body (i.e., Board of Supervisors, City Council, etc.)

BOARD OF SUPERVISORS
BOBBERG MANSUETI
2011 MAY 15 P 7:10

Date of Inspection: August 31, 2010 Inspected by: Mike Gain

Fire Authority: Modesto Fire Department

Facility Representative: Natascha Roof

**MODESTO FIRE DEPARTMENT**

P.O. BOX 642
 MODESTO CA 95353
 1010 10TH STREET STE. 3200
 (209) 571-5553

Page:1

FIRE SAFETY NOTICE**I-Inspection - Initial Annual FPB Assigned To GAIN, Michael on 8/31/2010**

Start Date: 8/31/2010 3:10:31PM **Finish Date:** 8/31/2010 3:12:20PM
Business Name: JUVENILE HALL **Occupancy ID:** 3618
Address: 2215 BLUE GUM AVE Unit No: * **Station No.:** Station 04
City/State/Zip: MODESTO, CA 95358 **Business Phone:** (209)525-4580

<u>Complex Info</u>	<u>Main Floor</u>	<u>Stories</u>	<u>Estimated Values</u>
Commercial Units: 0	Length: 0	Above Grade: 1	Property: \$0.00
Residential Units: 0	Width: 0	Below Grade: 0	Content: \$0.00
Complex Type: 1	Area: 0	Upper Construction: -	
Complex: JUVENILE HALL	Construction: -		

<u>Violations</u>	<u>Date Found</u>	<u>Date Cleared</u>	<u>Standard/Reference</u>
GENERAL			
Annual Inspection Pass	08/31/2010		

Recipient:

Natascha Roof

NATASCHA ROOF

A re-inspection shall be made on or after:

A \$77.00 FEE WILL BE CHARGED FOR THE 3RD AND ALL SUBSEQUENT INSPECTIONS

FIRE/LIFE SAFETY INSPECTION REPORT

ADULT/JUVENILE DETENTION FACILITIES

Facility:

FACILITY TYPE: (check one)

40-50-44-0003-000-040-L
STANISLAUS CO JAIL
805 12TH ST
MODESTO CA 95354

- Adult max/med security
- Adult minimum security
- Juvenile max/med security
- Juvenile minimum security
- Holding Cell(s) only

An inspection of this facility was conducted per the mandate of Section 13146.1, California Health and Safety Code, and applicable requirements of Titles 19 and 24, California Code of Regulations. (Check appropriate box)

- No deficiencies affecting fire/life safety were noted. Fire clearance is granted.
- Minor deficiencies affecting fire/life safety were noted and are pending correction. Fire clearance granted
- Fire clearance is withheld pending correction of deficiencies. (List of deficiencies is attached).
- Prisoners are no longer detained at this facility.

The authority conducting the inspection shall submit copies of this report to the appropriate bodies listed below. Where fire/life safety deficiencies are noted, a list of the deficiencies must accompany this report.

- Office of the State Fire Marshal
Fire & Life Safety Division
P.O. Box 944246
Sacramento, CA 94244-2460
FAX: (916) 324-3784
- Board of Corrections
Facilities Standards & Operations Division
600 Bercut Drive
Sacramento, CA 95814
FAX: (916) 327-3317
- Official In Charge of the Facility
- Local Governing Body (i.e., Board of Supervisors, City Council, etc.)

2011 MAY 16 11:56
BOARD OF SUPERVISORS

Date of Inspection: 3-30-2011 Inspected by: C. MOSSMAN

Fire Authority: Modesto Fire Dept

Facility Representative: SCOTT MURPHY - Deputy Sheriff.

The following is to be used only as a guide and is not intended to include all applicable codes and requirements.

A. CONSTRUCTION	Yes	No	N/A
1. Building construction type and fire resistive rating conform throughout and are maintained in good repair. (19 CCR 3.24; CBC 308.2.2.2; CBC 324A.1; CBC 324A.2; CBC Table 6-A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Proper interior ceiling and floor finish ratings are provided. (CBC 324A.4, CBC Table 8B)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
3. Vertical shaft enclosures are in good repair and fire assemblies at openings are properly maintained. (CBC 711, Table 6A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
B. EXITS			
4. Proper corridor construction and opening protection are provided and maintained. Dead-end corridors do not exceed 20 feet in length. (CBC 1004 through 1006). Exit balconies do not exceed 50 feet. (CBC 332A.4)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. All means of egress are unobstructed and free of storage. (19 CCR 3.11)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Means of egress and exit signs are installed, illuminated and maintained. (CBC 1003.2.8.2 through 1003.2.9.2; CBC 331A.5)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Corridors are not used as part of the air distribution system. (CMC 602.1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Supervisory personnel are continually on duty and effective provisions are made to remove occupants in case of fire or other emergency. (Penal Code 6030[c]; CBC 1003.3.1.8 exception 3)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
C. MECHANICAL/ELECTRICAL			
9. Fire and smoke dampers and similar devices are adequate, properly installed, maintained and tested. (CMC 606.1 & 2; CBC 713.10, 713.11)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. All heating, cooling and ventilation equipment is maintained satisfactorily. There are no visible defects. (CMC 109.2; 19 CCR 3.02)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Electrical wiring, fixtures and appliances are properly installed and operated. (19 CCR 3.01; CBC 3.24)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Emergency power is provided for minimal lighting and fire/life safety systems. (CBC 1003.2.9; CBC 328A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
D. HOUSEKEEPING			
13. Kitchen hoods, vents, ducts and filters are installed, adequate, are maintained in proper condition and are free of grease. (19 CCR 3.19, 3.24; CMC 501 through 510)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
14. All areas are free of unacceptable amounts of storage. (19 CCR 3.19)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
E. FIRE EXTINGUISHING/FIRE ALARM			
15. All portable fire extinguishers, automatic fire sprinkler systems, wet and dry standpipe systems are installed and maintained properly. (19 CCR 3.24; 19 CCR 3.29; 3.29A; NFPA 13)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Manual and automatic fire alarm systems, when installed, shall be properly installed and maintained. (19 CCR 3.24; CBC 330A; NFPA 72)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. The automatic fire alarm system is properly maintained. (19 CCR 3.24)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
F. TRAINING/PREPLANNING			
18. At least one person is on duty who meets the training standards established for general fire and life safety relating specifically to the facility. (Penal Code 6030[c])	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. Fire suppression preplanning inspections are conducted by the local fire authority at least every two years. (Penal Code 6031.1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Code references above are from the most recent SFM adopted codes. Note that code references for the CBC may be different for facilities constructed prior to the revision of this form.

Where any deficiency is identified, please provide specific information regarding the deficiency type and location (e.g., the fire alarm in Building C indicated a trouble alarm and must be repaired.)

**MODESTO FIRE DEPARTMENT**

P.O. BOX 642
 MODESTO CA 95353
 1010 10TH STREET STE. 3200
 (209) 571-5553

Page:1

FIRE SAFETY NOTICE**RIA-Reinspecton Annual Assigned To MOSSMAN, Craig on 4/12/2011**

Start Date: 4/12/2011 8:07:38AM
Business Name: STANISLAUS CO JAIL
Address: 801 11TH ST Unit No: *
City/State/Zip: MODESTO, CA 95354

Finish Date: 4/12/2011 8:43:40AM
Occupancy ID: 3149
Station No.: Station 01
Business Phone: (209)525-7905

<u>Complex Info</u>	<u>Main Floor</u>	<u>Stories</u>	<u>Estimated Values</u>
Commercial Units: 0	Length: 0	Above Grade: 3	Property: \$0.00
Residential Units: 0	Width: 0	Below Grade: 1	Content: \$0.00
Complex Type: 4	Area: 0	Upper Construction: -	
Complex:	Construction: -		

<u>Violations</u>	<u>Date Found</u>	<u>Date Cleared</u>	<u>Standard/Reference</u>
-------------------	-------------------	---------------------	---------------------------

EXITS**Obstructions****03/30/2011****04/12/2011****[S] CFC / 1030.2**

Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency.

1. 1ST FLOOR STAIRWELL BLOCKED. HAS BEEN MADE INTO A MEDICAL CLOSET. NOTE STAIRWAYS NEED TO STAY CLEAR 24/7.

GENERAL**Violation California Fire Code****03/30/2011****04/12/2011**

Violations of the California Fire Code shall be corrected

1. MARK ALL FLOOR LEVELS IN STAIR WELLS.

Fire-resistive construction ma**03/30/2011****04/12/2011****[S] CFC / 703.1**

All required fire-resistive construction shall be maintained. Such elements shall be visually inspected by the owner annually and shall be properly repaired, restored or replaced when damaged, altered, breached or penetrated.

1. CAULK ALL PENETRATIONS WITH FIRE CAULKING.

Annual Inspection Pass**04/12/2011****04/12/2011****Recipient:**

Scott Murphy #1684

SCOTT MURPHY-DEPUTY SHERIFF

A re-inspection shall be made on or after:

A \$77.00 FEE WILL BE CHARGED FOR THE 3RD AND ALL SUBSEQUENT INSPECTIONS

**MODESTO FIRE DEPARTMENT**

P.O. BOX 642
 MODESTO CA 95353
 1010 10TH STREET STE. 3200
 (209) 571-5553

Page:1

FIRE SAFETY NOTICE**I-Inspection - Initial Annual FPB Assigned To MOSSMAN, Craig on 3/30/2011**

Start Date: 3/30/2011 7:58:20AM
Business Name: STANISLAUS CO JAIL
Address: 801 11TH ST Unit No: *
City/State/Zip: MODESTO, CA 95354

Finish Date: 3/30/2011 10:32:01AM
Occupancy ID: 3149
Station No.: Station 01
Business Phone: (209)525-7905

<u>Complex Info</u>	<u>Main Floor</u>	<u>Stories</u>	<u>Estimated Values</u>
Commercial Units: 0	Length: 0	Above Grade: 3	Property: \$0.00
Residential Units: 0	Width: 0	Below Grade: 1	Content: \$0.00
Complex Type: 4	Area: 0	Upper Construction: -	
Complex:	Construction: -		

<u>Violations</u>	<u>Date Found</u>	<u>Date Cleared</u>	<u>Standard/Reference</u>
-------------------	-------------------	---------------------	---------------------------

EXITS

Obstructions	03/30/2011		[S] CFC / 1030.2
---------------------	-------------------	--	------------------

Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency.

1. 1ST FLOOR STAIRWELL BLOCKED. HAS BEEN MADE INTO A MEDICAL CLOSET. NOTE STAIRWAYS NEED TO STAY CLEAR 24/7.

SYSTEMS

Fire equipment maintenance	03/30/2011		[S] CFC / 901.6
-----------------------------------	-------------------	--	-----------------

Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times and shall be replaced or repaired where defective.

1. IN TUNNEL TO COURT HOUSE LAST SPRINKLER HEAD PRIOR TO COURT BUILDING CRASH GATE SPRINKLER HEAD IS PAINTED.

GENERAL

Violation California Fire Code	03/30/2011		
---------------------------------------	-------------------	--	--

Violations of the California Fire Code shall be corrected

1. MARK ALL FLOOR LEVELS IN STAIR WELLS.

Fire-resistive construction ma	03/30/2011		[S] CFC / 703.1
---------------------------------------	-------------------	--	-----------------

All required fire-resistive construction shall be maintained. Such elements shall be visually inspected by the owner annually and shall be properly repaired, restored or replaced when damaged, altered, breached or penetrated.

1. CAULK ALL PENETRATIONS WITH FIRE CAULKING.

Recipient:

SCOTT MURPHY-DEPUTY SHERIFF

A re-inspection shall be made on or after: 04-30-2011

A \$77.00 FEE WILL BE CHARGED FOR THE 3RD AND ALL SUBSEQUENT INSPECTIONS